FLUKE®
Calibration

PG7600 VACUUM RELIEF VALVE, P/N 401050, INCLUDES:

QTY	PART NO	DESCRIPTION
1	401050	Vacuum relief valve assembly
1	100272	Gland (on PG7600 VAC port)
1	101200	Collar (on PG7600 VAC port)
1	560002	Instruction Sheet



Vacuum relief valve is shown in the closed position.

GENERAL INSTALLATION

1. Remove gland, collar and plastic plug from the PG7600™ vacuum port.
2. Install gland and collar onto vacuum relief valve assembly.

   Collar threads left-handed. Ensure collar is fully threaded. The plastic plug is not used.

3. Screw the adaptor (as assembled) into the PG7600™ vacuum port. Torque to 15 Nm (Newton meter).

PN 3152405
April 2014
© 2014 Fluke Corporation. All rights reserved. Specifications are subject to change without notice.
All product names are trademarks of their respective companies.