FLUKE®
Calibration

PPC™/ MPC™ Vacuum Kit

P/N 3584473 (110V) - P/N 3584486 (220V)

Instruction Sheet

Vacuum Kit includes:

DESCRIPTION	QTY	PART NO.
Vacuum Pump Assembly	*1*	
Adaptor 3/8 in. Swage x 1/8 in. NPTM	*1*	*3141557*
Adaptor 3/8 in. Swage x 3/8 in. NPTM	*1*	*3480098*
Adaptor 3/8 in. Swage x 1/4 in. NPTM	*1*	*3134815*
3/8 in. O.D. Tubing (200cm)	*1*	*3232445*

The PPC/MPC Vacuum Kit should be installed as illustrated below. Fill the vacuum pump with oil before using. Read the Fast Vac instruction sheet for additional information.

The solenoid valve protects the vacuum pump when turned off. When the operator decreases pressure in a PPC, test gas will be exhausted through the valve. This ensures that the gas will not flow into the pump. The valve is electrically connected to the vacuum pump power switch and actuates automatically.



Figure 1: *Fast Vac Vacuum Pump Illustrated Parts*

PN 3523534
April 2014
© 2014 Fluke Corporation. All rights reserved. Specifications are subject to change without notice.
All product names are trademarks of their respective companies.