

Taylor Guitars warrants this product to be free from defects in material or workmanship (excluding batteries) for one (1) year for the original purchaser from date of retail purchase. It does not cover damages or wear resulting from accident, misuse, abuse, commercial use, or unauthorized adjustment and/or repair. Should this product require service (or replacement at our option), contact the retailer where you purchased the product. If they are unable to resolve the issue, please email support@taylorguitars.com and include a photo of your sales receipt, or call 1-800-943-6782.

There are no expressed warranties except as listed above. This warranty gives you specific legal rights, and you may have other rights which vary from state to state. For additional product information, or warranty information elsewhere outside the USA, please email support@taylorguitars.com

CE
Made in China



©2021 Taylor Guitars. Taylor, Taylor Guitars, the Taylor Guitars logo and other Taylor Guitars marks are registered trademarks of Taylor-Listug, Inc. in the U.S. and other jurisdictions. 3159 062021


Taylor Guitars Hygrometer



Thank you for purchasing a Taylor Guitars Hygrometer. Please read this instruction manual carefully before use. Keep these instructions handy for future reference.

FEATURES

- Easy-to-read digital LCD readouts.
- Dual display for temperature & humidity.
- Wide measuring range.
- Long battery life with just 2 AAA batteries (not included).
- Multi-purpose case for tabletop or wall mount.



HOW TO OPERATE

1. Insert batteries

Insert 2 AAA batteries in battery compartment at rear of unit with correct polarity.

2. Check display

In normal conditions, the dual display should immediately appear; if the temperature or humidity display is blank, remove the batteries and re-insert them. This should reset the display.

3. Adjust °C/°F

Move switch to the preferred temperature unit readings.


4. Changing batteries

When the displays appear to be fuzzy or dim, the batteries need to be replaced.

NOTE: Please recycle or dispose of batteries per local regulations.

WARNING: Batteries may pose a choking hazard. As with all small items, do not let children handle batteries. If swallowed, seek medical attention immediately.

CAUTION: Do not dispose of batteries in fire. Batteries may explode or leak. Remove the batteries if the unit will not be used for a long period of time.



SPECIFICATIONS

Measuring Range Humidity	10% to 95%
Temperature	-40°C to 70°C / -40°F to 158°F
Display Increments Humidity	1% from 30% to 83% (max. 3% for remainder of range)
Temperature	0.1°C 0.1°F
Accuracy Humidity	10% to 30%: $\pm 10\%$ at $25.0^{\circ}\text{C} \pm 0.5^{\circ}\text{C}$ 30% to 83%: $\pm 5\%$ at $25.0^{\circ}\text{C} \pm 0.5^{\circ}\text{C}$ 83% to 95%: $\pm 8\%$ at $25.0^{\circ}\text{C} \pm 0.5^{\circ}\text{C}$
Temperature	$\pm 2^{\circ}\text{C} \sim -40^{\circ}\text{C}$ to 0°C / $\pm 4^{\circ}\text{F} \sim -40^{\circ}\text{F}$ to 32°F $\pm 1^{\circ}\text{C} \sim 0^{\circ}\text{C}$ to 50°C / $\pm 2^{\circ}\text{F} \sim 32^{\circ}\text{F}$ to 122°F $\pm 3^{\circ}\text{C} \sim 50^{\circ}\text{C}$ to 70°C / $\pm 6^{\circ}\text{F} \sim -122^{\circ}\text{F}$ to 158°F
Power	2 AAA batteries (not included)
Battery Life	300 days for continuous reading
Dimensions	4.7 x 2.9 x 0.55 inches
Response Time	Max. 1 minute for both temperatures and humidity

IMPORTANT INFORMATION

- Do not drop unit. It is not shockproof.
- Do not soak the unit in water. It is not waterproof.
- Do not store the unit in direct sunlight or at a high temperature.
- Do not place the unit near strong magnets or high radiation, which may affect the accuracy.
- Do not attempt to disassemble the unit except to replace the batteries.
- Do not mix old and new batteries.
- Do not mix alkaline, carbon zinc (standard) or nickel cadmium (rechargeable) batteries.